

	Type	L #	Hits	Search Text	DBs	Comments	Error Definition	Errors
1	BRS	L1	56695	438/\$.cccls.	USPAT			0
2	BRS	L2	1235	1 and pattern\$3 near dielectric	USPAT			0
3	BRS	L3	35	2 and mold\$3	USPAT			0
4	BRS	L4	22	3 and press\$3	USPAT			0
5	BRS	L5	10	4 and align\$3	USPAT			0
6	BRS	L6	0	hofmann-james-j.ti.	USPAT			0
7	BRS	L7	15	(pattern\$3 near mold).ti.	USPAT			0
8	BRS	L8	15	(pattern\$3 near dielectric).ti.	USPAT			0
9	BRS	L9	2	8 and mold\$3	USPAT			0
10	BRS	L10	27	hofmann-james-j.in.	USPAT			0
11	BRS	L11	10	10 and mold\$3	USPAT			0
12	BRS	L12	2883	pattern\$3 near dielectric	USPAT			0
13	BRS	L14	1	13 and mold	USPAT			0
14	BRS	L13	20	12 and (contact near lithography)	USPAT			0
15	BRS	L15	42	1 and mold.ti.	USPAT			0
16	BRS	L16	0	15 and redistribution	USPAT			0
17	BRS	L17	6	15 and (conductive or bond\$3) near pad	USPAT			0
18	BRS	L18	33	1 and (press near mold)	USPAT			0